	September 2017 - 1917 - representation and configuration and confi	John Communication Communication (Communication Communication)	SOFTILE THE CONTROL OF THE CONTROL
978 9	0325Z 10 JAN 63 EECRET	Construction of the Constr	
om _	DIRECTOR) EO 12958 3.3(b)(1)>2	Yrs	C
118777	OSA (1,2,3,4,5,6,7,8,9,10)	PRIC	RITY
0 :	5/C (11)	Agentismone contravalentes se entre son esperiente de la contravalente del contravalente de la contravalente del contravalente de la contravalente de la contravalente del contravalente del contravalente de la contravalente del contravalente	ANTICO CONTROL OF THE PROPERTY
	TOR 0354Z 10 JAN 63		IN 61899
D F	PRITY	CITE	7635
C	XCART	· <u>L</u>	
N	O NIGHT ACTION	• .	
	1. ACFT 123 MADE FLIGHT NUMBER 30 ON 9 JAN	_63 FOR ONE	HOUR
. A	ND 51 MINUTES. (SECOND FLIGHT). TAKEOFF AT	1321 HOURS	
	GROSS WEIGHT 90,000 POUNDS, CG 20 PERCEN	T. PILOT J	IM
E	EASTHAM. PURPOSE OF FLIGHT: INERTIAL NAVIGATION SYSTEM, TYPE		
N	NUMBER ONE EQUIPMENT AND BACK-UP PITCH DAMPER CHECK.		
	2. NORMAL AFTERBURNER TAKEOFF AND CLIMB WITH LEVEL OFF		
A	AT 25,000 FEET AND 286 KEAS. ACFT PROCEEDED NORTHBOUND OVER		
T	TARGETS (ACFT CLIMBED		
T	TO 30,000 FEET AND 327 KEAS, TURNED 180 DEGREES AND PROCEEDED		
S	OUTHBOUND OVER CHECKPOINT AND	TARGETS.	ACFT
T	URNED 180 DEGREES PROCEEDED NORTHBOUND OVER		TARGETS
A	ND CHECKPOINT. ACFT CLIMBED TO 40,000 FE	ET AND 371	KEAS,
T	URNED 180 DEGREES AND PROCEEDED SOUTHBOUND OV	ER CHEC	KPO INT.
	CFT ACCELERATED TO 378 KEAS AT 40,000 FEET FO	R SOUTHBOUN	D PASS
A			

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

7635 (IN 61899)

PAGE TWO

AMACH FOR BACK-UP PITCH DAMPER CHECK. PULSED ACFT WITH

DAMPERS OFF. ACFT MADE 4 PITCH OSCILLATIONS BEFORE STABILIZING.

BACK-UP PITCH DAMPER WAS ENGAGED AND ACFT PULSED. ACFT MADE ONE

PITCH OSCILLATION AND STABILIZED. ACFT MADE INS FIX POINT CHECK

AT HOME PLATE THEN DESCENDED TO TRAFFIC PATTERN. LANDING AND

CHUTE DEPLOYMENT NORMAL. ACFT TAXIED TO INS FIX POINT AT NORTH

END OF AIRFIELD. INS INDICATED 8 MILE ERROR WHICH WAS CUMULATIVE

ERROR FROM START OF FIRST FLIGHT TO COMPLETION OF SECOND FLIGHT.

NO ADJUSTMENTS TO INS BETWEEN FLIGHTS AND FIRST SUCCESSFUL CON
TINUOUS OPERATION BETWEEN 2 FLIGHTS. INS AND TYPE ONE EQUIP
MENT APPEARED TO OPERATE SATISFACTORILY AT ALL CHECK POINTS.

BACK-UP PITCH DAMPER OPERATION CONSIDERED EXCELLENT. ACFT SCHE
DULED FOR ADDITIONAL INS CHECKS AND TYPE 3 EQUIPMENT CHECK ON

12 JAN 63. F-101 ACFT FURNISHED CHASE.

END OF MESSAGE